N° of the certificate: EST01041

Certificate of compliance of a trailer[1]
with the technical requirements for a safe lorry (greener, EURO3, ...)
As specified in Resolution CEMT/CM (2001)9

Vehicle Type and Make: FLIEGL SDS390

Vehicle Identification Number (VIN): WFDFLT33972002560

Sisu Auto Eesti AS Peterburi 75 Tallinn 11415 Estonia

The [2],

- Competent validation Services in the country of registration[3];
- ~~Vehicle Manufacturer, or the authorised Representative of the Manufacturer in the country of registration, or~~
- ~~A combination of the competent validation Services in the country of registration and the vehicle Manufacturer, or the authorised Representative of the Manufacturer in the country of registration, when all the equipment is not fitted by the vehicle Manufacturer.~~[4]

hereby confirms that the said vehicle is identical to the vehicle, which was on 12.09.2006, in compliance with the provisions of Resolution CEMT/CM(2001)9, and confirms that the particulars entered overleaf are correct.

The trailer is fitted with the following devices:

☑ ☐ Rear protective devices according to ECE/UN Regulation R.58/01 or to the Directive 70/221/EEC, as amended by Directive 2000/8/EC.

☑ ☐ Lateral protection according to ECE/UN Regulation R.73/00 or to the Directive 89/297/EEC.

☑ ☐ Warning lights according to ECE/UN Regulation R.6/01 or to the Directive 76/756/EEC, as amended by Directive 1999/15/EC.

☑ ☐ Rear marking plates (retroreflective) for heavy and long vehicles according to ECE/UN Regulation R.70/01

☑ ☐ Braking, including antiblocking systems, according to ECE/UN Regulation R.13/06 or to the Directive 71/320/EEC, as amended by Directive 98/12/EC.

Tallinn 14.09.2007

Place Date Signature(s) and stamp(s)

Sisu Auto Eesti AS Reg. nr. 10278707 RENAULT TRUCKS

1) Väljastatud 14.09.2007 kehtetul vormil;
2) SISU Auto Eesti AS ei ole pädev ametiasutus Eestis;
3) puudub viide tootja volitusele.

1. Semi-trailers included.
2. Delete inappropriate mentions.
3. For the countries where the Representatives of the manufacturers are not authorised.
4. In this case, the first signatory fills in the column on the left, the second signatory fills in the column on the right.